

### TEST REPORT

REPORT NO. : 2013MA0547	PAGE : 1 OF 8
This Test Report refers only to samples submitted by the applicant to SIRIM QAS International Sdn. Bhd. and tested by SIRIM QAS International Sdn. Bhd. This test report shall not be reproduced, except in full and shall not be used for advertising purposes by any means or forms without written approval from Managing Director, SIRIM QAS International Sdn. Bhd. Please refer overleaf for Conditions Relating To The Use of Test Report.	

Applicant : SKI PIPE & FITTINGS (M) SDN. BHD.  
43 Jalan TPP 5/13, Taman Perindustrian Puchong,  
47100 Petaling Jaya, Selangor Darul Ehsan,

Manufacturer : DONGYUAN KAIJIE METAL PROCESSING FACTORY,  
Huidieling Industrial Park, Xiantang Town,  
Dongyuan County, Heyuan City, Guangdong, China.

Product : **Fitting for pipe.**

Type of Test : 1. Hydraulic pressure test.  
2. Effect on water quality test.  
3. Intergranular corrosion test.

Reference Standard : 1. Manufacturer's requirement - Hydraulic pressure test.  
2. BS 6920: Part 1: 2000 - Effect on water quality test.  
3. ISO 3651 -2 - Intergranular corrosion test.

Description of sample :

Brand Name	SK-1
Model/Type	Refer from page 3 to 8
Quantity	One (1) of each model

Date received : 31/07/2013.

Description of test result : The submitted test samples as described in this test report **comply** with the requirement of the above Reference Standard.


Job No./Ref. No. : **J20131390547.**

Issued date : **27 FEB 2014**

Approved Signatories

  
(AHMAD NAZIEN B. ANUAR)  
Senior Technical Executive



  
(HJ. MOHD. ADZHAR B. AHMAD)  
HEAD  
Mechanical & Automotive Section (MAST),  
Testing Services Department,